

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:


None

No record of subsequent monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 035-2000.



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2" aluminum cap marked as shown below, 27" in the ground.

NEW BEARING TREES:

A 8" Diameter Western Larch bears N32°E, 23.65 feet, marked CE1/16 S13 BT.

A 6" Diameter Douglas Fir bears S51°E, 32.15 feet, marked X BT.

Set steel fence post approximately 1 ft. South of corner monument.


I hereby certify that the corner was monumented on November 15, 2000.
Witnesses: Norbert Volny and Greg Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Rick G. Robinson

OREGON
July 17, 1988
RICK G. ROBINSON
2219

Renewal Date December 31, 2000



UNION COUNTY
SURVEYOR

Date Received 11/22/00

Date Filed 12/27/00

Filed By *Greg T. Black*

File Number 034-2000C

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 17° East magnetic declination, and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2219 to the bearing tree blaze.