


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was not set in the original survey.



DIAGRAM

No record of subsequent monumentation found in Union County survey records

DESCRIPTION OF CORNER EVIDENCE FOUND:

Not applicable

See map of survey 037-1993

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:


At point determined by survey, I set a 5/8" X 30" rebar with aluminum cap marked as shown, 36 inches in the ground, from which;

NEW BEARING OBJECTS:

- A 5/8 x 30 inch rebar with aluminum cap bears N52°E, 55.90 feet marked NE RP
- A 5/8 x 30 inch rebar with aluminum cap bears S54°W, 29.39 feet marked SW RP

I hereby certify that the above corner point was perpetuated as hereon described on August 19, 1993.

Witnesses: Travis Foster, Pete Crabtree



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Handwritten signature*

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

UNION COUNTY  
SURVEYOR

Date Received 9/3/93

Date Filed 9/10/93

By Henry T. Blackman

File No. 048-1993R

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to the center of the aluminum cap.