


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not set in the original survey.



DIAGRAM

No record of subsequent monumentation found in Union County survey records.

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

Not applicable.

See map of survey 037-1993.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown, 22 inches in the ground, from which;

**BEARING TREES:**

A 14 inch Ponderosa Pine bears N26°E, 28.20 feet marked X BT

A 14 inch Ponderosa Pine bears S40°E, 63.95 feet marked CS 1/16 S14 BT


Set a steel fence post approximately 13 feet North  
Land Survey Monument sign attached.

I hereby certify that the above corner point was  
perpetuated as hereon described on August 17, 1993.

Witnesses: Travis Foster, Pete Crabtree

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
641



I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.

M-19

**UNION COUNTY SURVEYOR**

---

Date Received 8/13/93

Date Filed 9/10/93

By Gary T. Blackman

File No. 049-1993R