
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not set in the original survey.



No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Not applicable.

See map of survey 037-1993.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a $2\frac{1}{2}$ " x 30" aluminum pipe with aluminum cap marked as shown, 29 inches in the ground, from which;


BEARING TREES:

A 20 inch Ponderosa Pine bears $S64^{\circ}E$, 41.38 feet marked S 1/16 S13 BT A 26 inch Douglas Fir bears $N72^{\circ}W$, 70.45 feet marked S 1/16 S14 BT

Set a steel fence post approximately 5 feet South Land Survey Monument sign attached.

I hereby certify that the above corner point was perpetuated as hereon described on August 17, 1993. Witnesses: Travis Foster, Pete Crabtree





Date Received 9/3/93

Date Received 9/3/93

Date Filed 9/06/83

By Hypy 4 Blockn

File No. 050-1993 L

I used a steel tape and magnetic compass in the establishment of new accessories. I used 17° East magnetic declination and the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 644 to the BT blaze.