## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None

Survey 95-74 calls position for corner.

No record of subsequent monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 024-1997.

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap marked as shown below, 25" in the ground, with ring of stone.

## BEARING TREES:

A 9" Ponderosa Pine bears N 2° W, 9.0 feet, marked E1/16 S24 BT.

A 11" Ponderosa Pine bears S 66° W, 9.1 feet, marked E1/16 S25 BT.

I hereby certify that the corner was monumented on August 1, 1997. Witnesses: Jeff Madsen and Greg Blackman Jr.


REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

eteren

JEFFERY P. PETERSEN 2625

Ronewal Date: December 31, 1998



T1N R40E R-24

25

S

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 50d spike driven in the right side of the root crown. I attached a brass washer marked OPLS 2625 to the bearing tree blaze.

