


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was never established.




Description of corner evidence found:

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, Union County Survey No. 045-2002;

Set a 3 1/4 in. dia. alum. cap on a 5/8 in. dia. by 30 in. long iron rod, buried 17 ins. in the ground, the bottom 8 ins. being in a 5/8 in. dia. drill hole with rod being secured with Rockite cement, with mound of stone and t-post set 1.5 ft. northerly. Marked as shown:



From which:

A 5/8 in. dia. by 8 in. long iron rod with 1 1/2 in. dia. aluminum cap in a 5/8 in. dia. by 4 in. deep drill hole secured with Rockite cement, set in a rock outcrop 2.5 ft. by 4 ft. by 1 ft. high, mkd: RP NE bears N 87° E, 53.20 ft. dist.

A 5/8 in. dia. by 30 in. long iron rod with 1 1/2 in. dia. aluminum cap at northwesterly corner of rock jack, mkd. : RP SW bears S 42° W, 41.05 ft. dist.

I hereby certify that the corner was monumented as described and accessories were taken on Oct. 22, 2002, with a hand compass set at 18 1/2° E. declination and steel tape.

Witness: Peter C. Elder

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Peter C. Elder

OREGON
JULY 13, 1999
PETER C. ELDER
51277

Renewal Date: Dec. 31, 2003

UNION COUNTY
SURVEYOR
Date Received 12/2/02
Date Filed 12/31/02
By Hyun T. Olow
File No. 057-2002R