


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was never established.




Description of corner evidence found:

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, Union County Survey No. 045-2002;

Set a 3 1/4 in. dia. alum. cap on a 5/8 in. dia. by 30 in. long iron rod, buried 27 ins. in the ground, with rock collar and t-post set 0.8 ft. northwesterly. Corner is under large rock jack alongside corral.

Marked as shown:



From which:

A 5/8 in. dia. by 30 in. long iron rod with yellow plastic cap mkd: ELDER LS 51277 bears N 56° E, 10.0 ft. dist.

A 5/8 in. dia. by 30 in. long iron rod with yellow plastic cap mkd: ELDER LS 51277 bears S 26° E, 10.0 ft. dist.

I hereby certify that the corner was monumented as described and accessories were taken on Oct. 22, 2002, with a hand compass set at 18 1/2° E. declination and steel tape.

Witness: Peter C. Elder

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1999
PETER C. ELDER
51277

Renewal Date: Dec. 31, 2003

UNION COUNTY
SURVEYOR

Date Received 12/2/02

Date Filed 12/31/02

By [Signature]

File No. 055-2002R