


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner was never established.




Description of corner evidence found:

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, Union County Survey No. 045-2002;

Set a 3 1/4 in. dia. alum. cap on a 5/8 in. dia. by 30 in. long iron rod, buried 19 ins. in rock crack and secured with Rockite cement, with mound of stone and t-post set 0.9 ft. easterly.  
Corner is at edge of creek bed, 15 ft. east of centerline of creek.

Marked as shown:



From which:

A Ponderosa pine, 22 ins. dia. , bears N 57° E, 97.6 ft. dist.  
marked: SE 1/16 S29 BT

A cottonwood, 36 ins. dia., bears S 15° W, 58.4 ft. dist.  
marked: SE 1/16 S29 BT (bark scribed) .

I hereby certify that the corner was monumented as described and accessories were taken on Oct. 21, 2002, with a hand compass set at 18 1/2° E. declination and steel tape.

Witness: Peter C. Elder

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 13, 1999  
PETER C. ELDER  
51277

Renewal Date: Dec. 31, 2003

UNION COUNTY  
SURVEYOR

Date Received 12/2/02

Date Filed 12/31/02

By Peter C. Elder

File No. 054-2002R