# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**Section:** 

28/33

Township:

1 North

Range:

40 East of the Willamette Meridian

County:

Union

**Corner Indexing Information:** 

Township 1N Range 40E Corner Code V-11 (Willamette Meridian)

Additional Identifier: (e.g. BLM designation for the corner, street intersection, plat name, block, lot, etc.)

Quarter Corner common to Sections 28 and 33

### HISTORY OF ORIGINAL CORNER ESTABLISHMENT.:

The corner was originally established by Deputy Surveyors Odell & Gray under their joint contract No. 120 dated May 27, 1867. The Surveyor Generals records state:

Set post cor. for 1/4 Sec. drove charred stake and raised stone mound as per instructions.

#### **DESCRIPTION OF CORNER EVIDENCE FOUND:**

At the corner location found the remnants of a stone mound.

### Monument Set (Procedures & Description):

At the location of the stone mound, I set a 1 1/2" galvanized iron Pipe with a 2 1/4" brass cap marked as shown.

## **Monument Detail:**

T1N R40E

S28

1/4 ----

S33

2018

PLS 02820

#### **New Accessories:**

#### WE SET.

A 5/8 rebar w/ yellow cap stamped 'PBS WA 19619 OR 02820' attached which bears N45°08'E 25 feet from the corner.

A 5/8 rebar w/ yellow cap stamped 'PBS WA 19619 OR 02820' attached which bears S45°22'E 25 feet from the corner.

A 5/8 rebar w/ yellow cap stamped 'PBS WA 19619 OR 02820' attached which bears S45°00'W 25 feet from the corner.

A 5/8 rebar w/ yellow cap stamped 'PBS WA 19619 OR 02820' attached which bears N45°06'W 25 feet from the corner.

I hereby certify that the corner was perpetuated on July 5, 2018.

Surveyor's Seal

Firm/Agency: PBS Engineering & Environmental, Inc

5 N. Colville

Walla Walla WA 99362

Witness:

Felipe Hernandez **Todd Trondson** 

**UNION COUNTY SURVEYOR** 

Date Received 2

REGISTERED PROFESSIONAL LAND SURVEYOR