

UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by William H. Odell under GLO contract Number 120, dated May 27, 1867. Surveyor General record states:

Set post cor for Sec's 26, 27, 34, 35 drove charred stake and raised stone mound as per instructions.

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found rock jack fence corner at harmonious position

See Survey #028-1999

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED


TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At fence corner, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 24" in the ground with a mound of stone 3 feet from base to top of cap from which:

- A 5/8" x 30" rebar with aluminum cap bears N27°E, a distance of 6.70 feet, marked "BGB SURVEY MARKER NE RP".
- A 5/8" x 30" rebar with aluminum cap bears S72°E, a distance of 6.46 feet, marked "BGB SURVEY MARKER SE RP".
- A 5/8" x 30" rebar with aluminum cap bears S6°W, a distance of 6.55 feet, marked "BGB SURVEY MARKER SW RP".
- A 5/8" x 30" rebar with aluminum cap bears N63°W, a distance of 7.94 feet, marked "BGB SURVEY MARKER NW RP".

I hereby certify that the corner was monumented on July 20, 1999.
Witness: Norbert W. Volny, Gregory T. Blackman Jr.

T 1 N R 40 E V - 17




REGISTERED
PROFESSIONAL
LAND SURVEYOR

Rick G. Robinson

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date December 31, 1998



**UNION COUNTY
SURVEYOR**

Date Received 7/26/99

Date Filed 8/1/99

Filed By *Gregory T. Blackman*

File Number 021-1999/2

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to the center of the aluminum cap.