


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner was never established.




Description of corner evidence found:

Description of monument and accessories I established to perpetuate original location of this corner:

At the position determined by survey, Union County Survey No. 045-2002;  
Set a 3 1/4 in. dia. alum. cap on a 5/8 in. dia. by 30 in. long iron rod, buried 24 ins. in the ground, with rock collar and t-post set 1.5 ft. westerly.

Marked as shown:



From which:

A ponderosa pine, 18 in. dia., marked: CN 1/16 S32 BT, bears N 18° E, 14.0 ft. dist.

A 5/8 in. dia. by 30 in. long iron rod with yellow plastic cap mkd: ELDER LS 51277, set in center of a found rock mound (apparent unrecorded 1/16 cor.), 5 ft. dia. and 2 ft. high, bears S 73° E, 12.6 ft. dist.

I hereby certify that the corner was monumented as described and accessories were taken on Oct. 20, 2002, with a hand compass set at 18 1/2° E. declination and steel tape.

Witness: Peter C. Elder

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 13, 1999  
PETER C. ELDER  
51277

Renewal Date: Dec. 31, 2003

UNION COUNTY  
SURVEYOR

Date Received 12/2/02

Date Filed 12/31/02

By [Signature]

File No. 052-2002R