


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner not previously established.

Township 1 North, Range 40 East  
W-11




**Subsequent survey:**

None found

**Description of evidence found:**

None found.



**Description of monument and accessories established to perpetuate the location of this corner.**

Corner positioned by survey 023-2023. Set an aluminum pipe, 2 1/2 ins. diam., firmly set, projecting 6 ins. above the ground in a 3 ft. diam. stone mound, with 3 1/4 ins. aluminum cap mkd. as shown.

**New Accessories:**

- A basalt stone, 1 ft. by 2 ft. by 2 ft., bears S. 56° E., 30.2 ft. dist., marked XBO 1.
- A basalt stone, 2 ft. by 3 ft. by 1 ft., bears S. 77° W., 30.9 ft. dist., marked XBO 2.

Bearings are made with a hand compass, magnetic declination = 15°E.

**I hereby certify that the above corner point was perpetuated as herein described on 8/29/2023.**

Witnessed by:  
Matt Brockamp, LS  
Austin Brockamp

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*[Signature]*  
**OREGON**  
MAY 20, 2015  
MATTHEW R. BROCKAMP  
78556

Registration expires 12/31/2023

**UNION COUNTY  
SURVEYOR**

Date Received 9/16/23

Date Filed 9/18/23

Filed By [Signature]

File Number 047-2023R

**BROCKAMP LAND SURVEYING, LLC**  
www.brockamplandsurveying.com

Matt Brockamp, PLS  
541-398-0884  
matt@brockamplandsurveying.com

P.O. Box 553  
Wallowa, OR 97885

*Full Service Land Survey Firm*