CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1863 by Timothy W. Davenport, Deputy Surveyor under Contract No. 102.

Surveyor General's records states;
Set \(\frac{1}{4} \) sec. post. Made mound of rock.

Z-//
DIAGRAM

T 1 N R 40 E

1 S 33

1979

ORLS 645

Description of corner evidence found:

At assumed corner location I found mound of stone but no evidence of wood post. Corner location has been confirmed from east & west.

Description of monument and accessories i established to perpetuate the original location of this corner

I set a 2" galv. iron pipe with brass cap approx. 12" above surface of very rocky ground in a mound of stone 3 ft. dia. and 1 ft. high. Cap stamped as shown above.

No bearing trees are available.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

Office of	County of	
State of, I hereby certify i	that the within instrument was filed in (his office
for record on the day of	************	
ICOUNTY OFFICE AND ADDRESS OF THE PROPERTY OF	·	
(COUNTY OFFICIAL)	(DEPUTY)	
	· .	UNIO

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR	
Date Received	
Date Filed	
Ву	☆ GPO 796-333