CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishments

Corner established in 1863 by Timothy W. Davenport, Deputy Surveyor under Contract No. 102.

Surveyor General's records states:
Set \(\frac{1}{2} \) sec. post. Made mound of rock.

Z-15

DIAGRAM

T 1 N R 40 E

\$\frac{1}{4} \ SC \ 1979 \ ORLS 645

Description of corner evidence found:

At assumed corner location I found mound of stone and a large square rock crib placed alongside to the north and west of the corner location. Confirmed $\frac{1}{4}$ cor. location from the east and west along the base line. There is also evidence of an old fence line to the north.

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2" galv. iron pipe with brass cap approx. 18" above surface of very rocky ground in a large mound of stone $3\frac{1}{2}$ ft. dia. and 2 ft. high. Cap stamped as shown above.

No bearing trees avialable.

REGISTERED PROFESSIONAL LAND SURVEYOR

JOREGON JULY 10, 1964 JAMES H. HAMBLETON 645

winds Holain

Office of	County of
Office of	
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR	
Date Received	
Oate Filed	
☆ GPO 796-333 By	
File No. 100-84R	