CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1863 by Timothy W. Davenport, Deputy Surveyor under Contract No. 102.

Surveyor General's records states:
Set post, cor. to secs. 34 and 35. Made mound of rock.

<u>Z-17</u>	
DIAGRAM	
Tln R40E SC	
S 34 S 35	
1979 ORLS 645	•

Description of corner evidence found:

At assumed corner location I found mound of basalt stone. Mound of stone has hollow center as if a post had been in the mound.

Found a stone $16 \times 8 \times 8$ " upright in mound; appeared to have been set in place or alongside the original wooden post which has long since rotted away.

Description of monument and accessories I established to perpetuate the original location of this corner

I set a 2" galv. iron pipe with brass cap approx. 12" above surface of ground in a mound of stone 3 ft. dia. and $l\frac{1}{2}$ ft. high. Cap stamped as shown above.

No bearing trees available.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 10, 1754 JAMES H. HAMBLETON 645

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR
Date Received
Date Filed
Ву
File No. 101-84-R