


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None



DIAGRAM

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

See Union County survey 002-1994.


DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

The corner position falls in a roadway. A railroad spike was set in the corner position.

From which:

A 12" Ponderosa Pine bears S25°E, 88.59 feet, marked "CN1/16 S7 BT".

A 2 1/2" x 30" aluminum pipe with aluminum cap reference monument marked as shown below bears south, 90.89 feet.



I hereby certify that the above corner point was perpetuated as hereon described on January 25, 1994. Witness: Jeff Petersen, Mike Schlegel.

UNION COUNTY SURVEYOR

Date Received 2-10-94

Date Filed 3-17-94

By Gregory T. Blaca

File No. 006-1994 R

REGISTERED PROFESSIONAL LAND SURVEYOR

Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
014

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 60d nail driven into the right side of the root crown.