


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

None



**DIAGRAM**

No record of subsequent monumentation found in Union County survey records.

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

See Union County survey 002-1994.


**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At computed position, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 30" in the ground, from which;

A 13" Tamarack bears N1°E, 50.05 feet, marked "CS 1/16 S7 BT".

A 13" Douglas Fir bears S9°E, 17.09 feet, marked "CS 1/16 S7 BT".

Drove steel fence post 5' north.



I hereby certify that the above corner point was perpetuated as hereon described on January 25, 1994.  
Witness: Jeff Petersen, Mike Schlegel.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>2-10-94</u>
Date Filed	<u>3-17-94</u>
By	<u>Morgan T. Black</u>
File No.	<u>011-1994 R</u>



I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 60d nail driven into the right side of the root crown.