


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None



DIAGRAM

No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Survey 95-74 shows position for corner.

See Union County survey 002-1994.


DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At computed position, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 30" in the ground, from which;

A 16" Douglas Fir bears S37°E, 19.50 feet, marked "SE 1/16 S7 BT".

A 16" Douglas Fir bears S50°W, 23.14 feet marked "X BT".

Drove steel fence post 5' north.



I hereby certify that the above corner point was perpetuated as hereon described on January 24, 1994.
Witness: Jeff Petersen, Mike Schlegel.

UNION COUNTY SURVEYOR	
Date Received	<u>2-10-94</u>
Date Filed	<u>3/17/94</u>
By	<u>Gregory T. Slaska</u>
File No.	<u>012-1994R</u>

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1994
DUANE I. GRIFFITH
644

I used a steel tape and magnetic compass in the establishment of new accessories. I used 20° East magnetic declination and the distances are to a 60d nail driven into the right side of the root crown.