


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-08

History of original corner establishment:

Note: This corner was previously established incorrectly in Survey of Record File No. 295-86R, recorded December 5, 1986. The monument described therein has been removed and placed and described below.



Description of corner evidence found:

Found 2.5" aluminum capped aluminum pipe marked: T1N R41E
Steel fence post.

E1/16S32

From the corrected corner position,

RLS 1848

Bearing trees found:

1986

12" Ponderosa Pine bears N34 3/4°E, 65.3 ft., blazed&scribed: E1/16S32BT.

11.5" Doug. Fir bears N52 1/4°W, 28.9 ft., blazed & scribed: E1/16S32BT.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is marked:

Corner set by proportioning.

T1N R41E

I set a 2.5"x30" aluminum capped aluminum pipe rising 12" in a mound of stones.

E1/16S32

Set steel fencepost 3 ft. East of corner.

RLS 1848

1987

Used existing bearing trees.

Painted blazes and attached signs as per Standard Specifications For Cadastral Surveys, USFS Region 6, March 1982. A 3/4" brass disk stamped "RLS 1848" was nailed to the lower ends of the blazes.

From intersection of 6200530 with road on ridgetop 3/4 mi. North of 6200, follow road NE 1/2 mi., then SE 1/4 mi., crosses creek, NE 1/4 mi. Road ends at fence line on North slope of small knob. North 300 ft. to posted line. Follow posted line East down hill 700 ft. to corner on East slope.

Compass Declination: 19 1/2°E

Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on August 13, 1987.



UNION COUNTY SURVEYOR
Date Received 1-25-88
Date Filed 1-26-88
By G. LANGLITZ, DEPUTY
File No. 59-88 R

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....


..... by
(COUNTY OFFICIAL) (DEPUTY)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-08

History of original corner establishment:

None.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is marked:

Corner set by proportioning.
I set a 2½"x30" aluminum capped aluminum pipe rising 12" in mound of stones.
Set steel fencepost 3 ft. West

T1N R41E
E1/16S32
RLS1848
1986

New BT's:

A 12" P. Pine bears N31½°E, 62.3 ft., blazed&scribed: E1/16S32BT
An 11½" Doug. Fir bears N58¼°W, 32.4 ft., blazed&scribed: E1/16S32BT

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. A ¾" brass disk stamped "RLS 1848" was nailed to the lower ends of the blazes.

From intersection of 6200530 with road on ridgetop ¼ mile North of 6200, follow road NE ½ mile, then SE ¼ mile, crosses creek, NE ¼ mile road ends at fence line on North slope of small knob, North 300 ft. to posted line. Follow posted line East down hill 700 ft. to corner on East Slope

Compass Declination: 19½°E
Witness: Jeremy Sutton

I hereby certify that the above described corner monument and/or accessories were established as hereon described on Oct. 15, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>B. A. Sutton</i>
OREGON JULY 13, 1979 B. A. SUTTON 1848

UNION COUNTY SURVEYOR
Date Received <u>12-5-86</u>
Date Filed <u>12-5-86</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>295-86R</u>

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)