USDA-FOREST SERVICE 6P0 940	»117	開發展 化自己剂 整型的形成 日	
Index File No. A - 9	CORNER RECOI	RD (SEARCH) Tract or 5m 7151.4) Survey No.	Cor. No
T 25 R. 36E	R.D. LAGRANDE	County Clared	· · · · · · · · · · · · · · · · · · ·
Merid. WILL	N.F. W-W	State OREGON	
CORNER DIAGRAM TIS TZS A A	DESCRIBE CORNER MONU  NONE  DESCRIBE BEARING TREES		ES FOUND
PHOTO IDENTIFICATION DATA 7/8/6/ Photo No. ENW 4-188 Filed At. Object Ident.	G000 28" P.P. Cu 4 14" LARCH T	CONDITION IN SEC 18. GOOD COND. U. DEAD & DOWN SCRIB	SABLE SCRIBING IN S4
PLANE COORDINATE POSITION DATA  State Zone  X Y	Z A A A A A A A A A A A A A A A A A A A		MES, ALSO HOW TO KENON GONNER
Signature  DA LITTOR	Title Divi	sion Headquorters	Date 7100-52 (3/68) 5

A-9

## TIFIED RECORD OF LAND CORNER MONUMENTATION

#### HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by John A. Hurlburt under GLO Contract Number 201, dated August 5, 1873. Surveyor General record states:

Set a pine post, 4 ft. long, 4 ins. square, 2 ft. in ground for cor to Sec 4, 5, 32 and 33. Tamarack 12 in. dia. N30°W 16 lks. Tamarack 18 in. dia. S34°W 30 lks.

Pine 18 in. dia. S69°E 13 lks.

Tamarack 24 in. dia. N82°E 35 lks.

Union County monumentation record 174-87R is a Forest Service corner record. Record states: 18" Larch, Standing, Dead scribing visible in good

28" P.P Live, good conditions, visable scribing in S4.

14" Larch dead and down scribing visible.

# S 33

T1S R36 EZ-09

### **DESCRIPTION OF CORNER EVIDENCE FOUND:**

condition in Sec 5

Found a steel fence post with BLM K-tag, from which:

A 30 inch pine stump bears South 69° East, a distance of 8.58 feet, no scribe marks visible.

A downed log with BT tag attached falls in the Northwest quadrant, no scribe marks visible, location indeterminate.

### DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the record bearing and distance from the pine stump, I set a 2  $\frac{1}{2}$ " x 30" aluminum pipe with 2 ½" aluminum cap, marked as shown below, 26 inches in the ground, from which:

An 8 inch White Fir bears North 18° East, a distance of 10.50 feet, marked T1S R36E S33 BT.

An 8 inch Ponderosa Pine bears South 43° East, a distance of 59.35 feet, marked T2S R36 S4 BT.

A 4 inch Ponderosa Pine bears South 42° West, a distance of 25.00 feet, marked X BT. An 11 inch White Fir bears North 79° West, a distance of 22.50 feet, marked T1S R36E S32 BT.

I set a steel fencepost 1 foot East of the corner monument.

I hereby certify that the corner was perpetuated on October 30, 2012.

Witness: Rick Robinson

REGISTERED **PROFESSIONAL** LAND SURVEYOR

JEFFERY S. HSU 83571

OREGON

Renewal Date: June 30, 2013

T1S **R36E** S 32 S 33 T2S 2012 **OPLS 83571** 

UNION COUNTY **SURVEYOR** Date Received 11/17 074-2012R

I used a steel tape and magnetic compass in the recovery of the bearing tree and establishment of new trees. I used 16° East magnetic declination and the bearings and distances are to the center of root crown on old bearing tree. Distance is to a 60d spike in the right hand side of the new trees. Bearing is to a brass washer marked OPLS 83571 in the lower BT blaze.