


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-19
~~2-19~~

History of original corner establishment: Corner established in 1882 by Herman D. Gradon, under General Land Office Contract No. 452.

Surveyor General Records (Notes) states:
Pine post 4' long 3" thick 2' in ground from which a pine 15" dia. bears N14°E 138 lks. dist.
A fir 20" dia. bears S14°W 75 lks.




(No subsequent remonumentations in county records)

Description of corner evidence found:

Found 24 in. ponderosa pine, live in good condition, marked 1/4 S, positioned 1/4 corner between Section 35 and 2, S14°W, 91 ft. dist. from notch in blaze.

Description of monument and accessories established to perpetuate the original location of this corner

Set 30 in. x 2 1/2 in. iron pipe with 3 in. brass cap marked as shown 6 in. in the ground to solid rock and chiseled an "X" in rock under pipe for the 1/4 Section Corner between Sections 35 & 4, and raised a mound of stone 4 ft. in diam. and 2 1/2 ft. high around the pipe, from which new BT's -
A 20 in. fir bears S60°W 86.9 ft. marked T2S R36E 1/4 S2 BT.
Measurement taken to a brass washer in face of blaze. Set steel fence post approximately 5 ft. west with warning sign attached.



Used steel tape and magnetic compass with declination = 20° East.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Douglas M. Ferguson
**OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848**

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the day of 19....., at..... o'clockm., (signed)
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
Date Filed _____
By _____
File No. 225-84 R