

## **CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

Land Surveying & **Boundary Consulting** 

P.O. Box 19 Mill City, OR 97360 (503) 897-2722

#### History of original corner establishment:

Corner not previously set.

# **A-8** CAP DIAGRAM E 1/16 S 5 PLS 2456 2003

## Description of corner evidence found:

Corner not previously set.

#### Description of monument and accessories I established to perpetuate the original location of this corner:

Monuments Set:

A 3 1/4" aluminum cap, marked as shown, on a 2 1/2" x 30" aluminum pipe (standard U.S.F.S. aluminum monument) 26 ins. in the ground with a rock collar. Accessories Set:

A Douglas fir, 11 ins. diam., bears S 17° E 13.7 ft. marked E 1/16 S5 BT on a double blaze with a brass washer marked PLS 2456.

A Douglas fir, 10 ins. diam., bears S 39 1/2° W 19.0 ft. marked E 1/16 S5 BT on a double blaze with a brass washer marked PLS 2456.

Red paint, posts and signs added as needed.

NAD 83 (CORS 2002):

Geographic

State Plane (North Zone)

45°30'52.7926" N

N 208,180.605 Meters

118°04'55.6981" W

E 2,688,881.559 Meters

Convergence 1° 42'53"

Equipment: Staff compass, Var. 18° E, loggers tape,

clinometer

Date: Sept. 2, 2003

Crew: Ron Walter, Collin Edwards-Hill, Michael

Cordoza

See also the Record of Survey filed concurrently with this certification.

**REGISTERED PROFESSIONAL** LAND SURVEYOR

> **OREGON** July 25, 1990 Evelyn R. Kalb 2456

EXPIRES: 06/30/2005

# **UNION COUNTY SURVEYOR**

Date Received 12

Date Filed

File Number <u>056</u>-2003R