1-11


History of original corner establishment:

Corner established by Union County Surveyor J.L. Curtis in survey dated October 30th, 1893 recorded in Old Book, page 304

Curtis set a post for the center of Section 16, T 1S, R 38 E, W.M. from which;

A pine 18 in. diameter bears N 77°30' E, 96 1ks.

A pine 36 In. diameter bears \$ 74°30' W, 54 1ks.



Description of corner evidence found:

Found the Southwest bearing tree, a rotted stump, scribes visible, Found stump hole in the position of the Northeast bearing tree


Description of monument and accessories I established to perpetuate the original location of this corner:

At record bearing and distance from the Southwest bearing tree, I set a $2\frac{1}{2}$ x 30" aluminum pipe with cap marked as shown, 26" in the ground with mound of stone, from which;

A 14" white fir bears North 88° East, 6.8 feet, marked C 坛. \$16 BT

A 14" pine bears South 66° West, 27.7 feet, marked C4 S16 BT

I used a magnetic compass and steel tape (declination 200 East) in the establishment of these accessories. distance measured to the center of the bearing trees.



REGISTERED **PROFESSIONAL** AND SURVEYOR

OREGÓN JULY 10, 1964 DUANE I. GRIFFITH

..... County of UNION

HOWARD L. PERRY DV JOIN

(COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received

Date Filed

File No. 105-84 R