
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.

DESCRIPTION OF CORNER EVIDENCE FOUND: None.

See Survey Number 017-2011.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:



At the position determined by Survey: I set a 5/8"x 30" rebar with 2 $\frac{1}{2}$ " Aluminum cap marked as shown below, 30" in the ground, from which;

NEW BEARING TREES:

A 5/8"x30" iron pin with 1 ½" aluminum cap bears South 55°25'36" East, a distance of 62.27 feet, marked SE RP.

A 5/8"x30" iron pin with 1 ½" aluminum cap bears South 58°43'38" West, a distance of 60.79 feet, marked SE RP.

I hereby certify that the corner was monumented on July 24, 2011. Witnesses: Jeff Hsu, Greg Blackman, Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2012

	GRIFFITH & TIS R38E SW 1/16	<u> </u>
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	T1S R38E	of ACT
	SW 1/16	3 P Z
	S22	
	2011	
	OPLS 2219	

UNION COUNTY SURVEYOR		
Date Received 7/19 / 2011		
Date Filed 7/19/11		
Filed By Lyg 7. Me		
File Number 036-2011		

I used a leica 1200 GPS unit in the establishment of new accessories. Thebasis f bearing is the same as that of survey number 017-2011. The distances to the accessories are to the center of the cap.