## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously established.

No record of subsequent monumentation found in UNION COUNTY survey records.

Description of corner evidence found:

See Survey Number 017-2011.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the corner position: I set a 5/8"x 30" rebar with 2 ½" Aluminum cap marked as shown below, 30" in the ground, from which;

## T1S R38E U-10 S 28

## **NEW BEARING TREES:**

A 8" Douglas Fir bears North 63° East, a distance of 31.75 feet, marked SW1/16 S28 BT.

A 7" White Fir bears South 59° East, a distance of 31.35 feet, marked SW1/16 S28 BT.

I hereby certify that the corner was monumented on June 15, 2011.

Witness: Gregory T. Blackman Jr. and Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON

Renewal Date: December 31, 2012

2219

T1S R38E

SW 1/16 S28

2011

OPLS 2219

UNION COUNTY SURVEYOR

Date Received 7/19/2011

Date Itelesive

.

File Number 032-7011K

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 16° East. The distance to the bearing trees are to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.