## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner established by David P. Thompson under GLO Contract number 103, dated September 3, 1863. Surveyor General record states:

Set Post at 1/4 corner position from which;

A Pine 24 in. Dia. Bears S 85°E, 300 lks dist

A Pine 24 in. Dia. Bears N85°E, 290 lks dist

No record of subsequent monumentation found in UNION COUNTY survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 017-2011.

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by Survey, I set a 1" x 30" iron pipe with 2  $\frac{1}{2}$ " Brass cap marked as shown below, 32" in the ground, from which:

## **NEW BEARING TREES:**

A 17" Douglas Fir bears North 18° East, a distance of 56.09 feet, marked 1/4 S28 BT.

A 20" Ponderosa Pine bears South 43° East, a distance of 9.04 feet, marked 1/4 S33 BT.

A 19" Douglas Fir bears South 61° West, a distance of 13.04 feet, marked 1/4 S33 BT.

A 21" Ponderosa Pine bears North 27° West, a distance of 67.38 feet, marked 1/4 S28 BT.


I hereby certify that the corner was monumented on June 14, 2011.


Witness: Gregory T. Blackman Jr. and Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2012





T1S R38E V-11

28

S

I used a steel tape and magnetic compass in the establishment of new accessories. The magnetic declination used was 16 East. The distance to the bearing trees are to a 50d spike driven on the right side of the tree at the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.