


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by Timothy Davenport as part of GLO contract # 102 dated July 20, 1863. Surveyor General field notes state: Set qr sec post on South face ledge E & W, made mound of stone.

T 1 N R 39 E Z-11



Corner recovered by J. Kimbrell in Old book of Surveys Page 192. No description given.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a prominent rock jack on East/West ledge in North/South bearing fences which is harmonious with corner position.

SEE SURVEY NUMBER 011-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the South East corner of found rock jack, I set a 2 1/2" x 30" aluminum pipe with a 3" aluminum cap marked as shown, 10" in the ground with mound of stone 3' base to top of cap.
From which:

NEW BEARING OBJECTS:

- A rock outcrop bears North 68°31' East, a distance of 18.17 feet, marked X BO.
- A rock outcrop bears South 55°10' East, a distance of 19.88 feet, marked X BO.
- A rock outcrop bears South 24°30' West, a distance of 16.01 feet, marked X BO.
- A rock outcrop bears North 69°19' West, a distance of 15.10 feet, marked X BO.

I hereby certify that the corner was perpetuated on April 6, 2018.

Witness: Kyle A. Tucker

REGISTERED PROFESSIONAL LAND SURVEYOR
[Signature]
OREGON June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGETT - GRIFFITH & BLACKMAN
T1N R39E
1/4 — S33 —
S4
T1S
2018
OPLS 83571

UNION COUNTY SURVEYOR
Date Received 4/25/18
Date Filed 4/25/18
Filed By [Signature]
File Number 012-2018R

I used an RTK GPS in the establishment of the new accessories. Basis of Bearing is as per Survey 011-2018. The distances are to the center of the X chiseled in stone.