CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by David P. Thompson under GLO Contract Number 103, dated July 3rd, 1863. Surveyor General Field Notes state:

Set post for 1/4 sec corner from which

A Pine 8 in. diam bears N70°E 75 lks dist A Pine 15 in. diam bears S10°E 29 lks dist T1S R39 E N-23 13 S

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

Boise Cascade loc. tag found on adjacent tree

SEE SURVEY NUMBER 019-2023

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position I set a 2 1/2" by 30" aluminum pipe, 25 inches in the ground, with 3" aluminum cap marked as shown below, in a mound of stone 2 feet in diam., from which:

NEW BEARING OBJECTS:

A 6" White Fir bears North 27° East, a dist. of 11.55 feet, marked 1/4 S13 BT A 16" Douglas Fir bears South 32° East, a dist. of

26.90 feet , marked 1/4 S24 BT.
A 6"Douglas Fir bears South 24° West, a dist. of

7.15 feet, marked 1/4 S24 BT.

A 15" Douglas Fir bears North 55° West, a dist. of

17.50 feet, marked 1/4 S13 BT.

Set steel fence post approx. 1.5 feet West of monument.

I hereby certify that the corner was monumented on August 14th, 2023.

Witness: Adam Gordon

BLACKMAN T1S R39E **S13** 1/4 **S24 OPLS 83571** 2023

REGISTERED **PROFESSIONAL** LAND SURVEYOR OREGON JEFFREY S. HSU

83571 Renewal Date: June 30, 2025

UNION COUNTY SURVEYOR

I used a tape and compass in the establishment of the new accessories. Bearing is measured to a brass washer labeled OPLS 83571 located at the center of BT blaze, with a declination of 14° East. Distance is measured to a 60d spike nailed to the right side base of tree.