
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None

T1S R39 EQ-18



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 019-2023

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 30" iron pin, 27" in the ground, with a 2 1/2" aluminum cap, from which:

## NEW BEARING OBJECTS:

A 16" Douglas Fir bears North 81° East, a dist. of 38.45 feet, marked SW 1/16 S23 BT. A 9" Douglas Fir bears South 10° East, a dist. of 40.85 feet, marked SW 1/16 S23 BT.

Set steel fence post 1 foot West of monument.

Falls approx. 13 ft. South of East/West fence line

I hereby certify that the corner was monumented on August 16th 2023.

Witness: Adam Gordon

GRIFFITH & SLACALLY SW 1/16 S23

OPLS 83571
2023

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2025

I used a steel tape and magnetic compass in the establishment of the new accessories. I used a magnetic declination of 14° East. Distances are to a 60d spike driven into the right side base of tree. Bearings are to a brass washer marked OPLS 83571 in the BT blaze of the new bearing tree.

UNION COUNTY
SURVEYOR

Date Recaived 9/5/23

Date Filed By 032 2023 2