

**UNION COUNTY SURVEYOR**

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:  
NONE

DESCRIPTION OF CORNER EVIDENCE FOUND:  
NONE

See Union County Survey 033-1998


DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position determined by survey, I set a 2½" x 30" aluminum pipe with aluminum cap marked as shown below, 22" in the ground with a 2 ft. Mound of stone, base to top, from which:

- A 5/8" iron pin with 1/1/2" aluminum cap bears S65°W, a distance of 12.42 feet, marked BGB SURVEY MARKER X RP.
- A 5/8" iron pin with 1/1/2" aluminum cap bears S64°E, a distance of 7.00 feet, marked BGB SURVEY MARKER Z RP.
- A 5/8" iron pin with 1/1/2" aluminum cap bears S52°W, a distance of 5.48 feet, marked BGB SURVEY MARKER W RP.
- A 5/8" iron pin with 1/1/2" aluminum cap bears S53°E, a distance of 9.44 feet, marked BGB SURVEY MARKER Y RP.

I hereby certify that the corner was monumented on August 24, 1998.  
Witness: Jeff Madsen, Norbert Volny, Greg Blackman Jr.

T 1 S R 40 E A-11




REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Rick G. Robinson*

OREGON  
July 17, 1986  
RICK G. ROBINSON  
2219

Renewal Date December 31, 1998



**UNION COUNTY SURVEYOR**

Date Received 9/2/98

Date Filed 9/26/98

Filed By *Greg T. Blackman*

File Number 067-1998R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to the center of the caps on the reference pins.