## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history.

DIAGRAM
T 1 S R 40 E
E-C-1/16
S 10
1980

ORLS 645

G-16

Description of corner evidence found:

None

Description of monument and accessories i established to perpetuate the original location of this corner

I set a 1" galv. iron pipe 30" long with a brass cap, 6" above surface of ground in a mound of stone, with cap stamped as shown above. I set two bearing trees:

A 14" fir bears N 42 15 W, 22.90 feet and scribed 1/16 S BT. A 14" fir bears S 24 00 W, 20.86 feet and scribed 1/16 S BT.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Varias Holamb Lon
5-20-80

OREGON
JULY 10, 1964
JAMES H. HAMBLETON

645

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR
Date Received
Date Filed
Ву
File No. 152-84R

#### CERTIFIED RECORD OF LAND CORNER MONUMENTATION


## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by James Hambleton in Survey Number 38-80. Union County Monumentation record 152-84R states:

I set a 1" galv. iron pipe 30" long with brass cap 6" above surface of ground in a mound of stone. I set two bearing trees:

A 14" fir bears N42 15W, 22.90 feet and scribed 1/16 S BT. A 14" fir bears S24 00W, 20.86 feet and scribed 1/16 S BT.

## T1S R40 EG-16



### DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 1" iron pipe with 2 1/2" brass cap, marked as shown below, protruding 3" above ground in a collar of stone 3 ft. diam., from which:

A 22" stump bears South 24° West, a distance of 20.9 feet, blaze evident. A 26" stump bears North 41° West, a distance of 21.7 feet, blaze evident.

SEE SURVEY NUMBER 018-2017


# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe monument,

#### NEW BEARING TREES:

A 12" Douglas Fir bears North  $67^{\circ}$  East, a distance of 10.35 feet, marked CE 1/16 S10 BT. A 12" Douglas Fir bears South, a distance of 27.10 feet, marked CE 1/16 S10 BT.

I hereby certify that the corner was perpetuated May 29, 2017.




REGISTERED
PROFESSIONAL
LAND SUPPEYOR

OREGON
June 2, 2010

JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer in the lower BT blaze marked OPLS 83751. Distances are to a spike in the side of the root crown.