


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 1 S R 40 E H-05



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 026-2022

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8" x 30" iron pin, 28" in the ground, with 2 1/2" aluminum cap marked as shown, from which:

NEW BEARING OBJECTS:


An 11" Douglas Fir bears North 80° East a dist. of 5.60 ft., marked S 1/16 S8 BT.
A 6" Douglas Fir bears South 30° West a dist. of 18.55 ft., marked S 1/16 S7 BT.

Set steel fence post approx. 0.5 ft. South

North/South bearing fenceline bears approx. 3' West

I hereby certify that the corner was monumented on August 24, 2022.

Witness: Dan S. Drum, Kyle A. Tucker



REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2023

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY
SURVEYOR
Date Received 8/31/22
Date Filed 8/31/22
Filed By *[Signature]*
File Number 027-2022R