
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T1S R40 EH-07



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 026-2022

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position by survey, I set a 5/8" x 30" iron pin, 26" in the ground, with 2 1/2" aluminum cap marked as shown and in a 2 ft. diam. collar of stone, from which:

NEW BEARING OBJECTS:

A 7" Ponderosa Pine bears North 79° East a dist. of 23.85 ft., marked CS 1/16 S8 BT. A 7" Ponderosa Pine bears South 4° East a dist. of 27.15 ft., marked CS 1/16 S8 BT.

Set steel fence post approx. 1 ft. West

Fence corner to West/South bearing fencelines bears approx. 60' Southwesterly

I hereby certify that the corner was monumented on August 24, 2022. Witness: Dan S. Drum, Kyle A. Tucker S 1/16 S8

C

OPLS 83571

2022

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2023

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY
SURVEYOR

Date Received 8/31/22

8/31/22

Filed Ey 2/22

File Number 028-2022