# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No previous history.

フーバ DIAGRAM T1S R 40 E W 1/16 S 10 S 15 1980 ORLS 645

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

I set a l inch galv. iron pipe 30" long with a brass cap, 4 inches above surface, in a mound of stone, with cap stamped as shown above. I set two bearing trees:

An 8" fir bears N 53 39 E, 24.75 feet and scribed 1/16 S BT.

An 10" fir bears S 23 47 E, 40.33 feet and scribed 1/16 S BT.

PROFESSIONAL LAND SURVEYOR

5-20-80

OREGON JULY 10, 1964 JAMES H. HAMBLETON

Office of	. County of
State of, I hereby certify for record on the day of	that the within instrument was filed in this office.
	by(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Filed\_\_\_\_

Fi'e No. 167-84 R

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

# HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner originally established by James Hambleton in Survey No. 32-80, dated 5-20-80. Union County mounumentation record states:

I set a 1" galv. iron pipe 30" long with a brass cap, 4" above the surface, in a mound of stone, with cap stamped as shown below. I set two new bearing trees:

An 8" fir bears N 53 39 E, 24.75 feet and scribed 1/16 S BT. A 10" fir bears S 23 47 E, 40.33 feet and scribed 1/16 S BT.

# T 1 S R 40 E J-14 S 15

## DESCRIPTION OF CORNER EVIDENCE FOUND:

Found a 2  $\frac{1}{2}$ " iron pipe with 2  $\frac{1}{2}$ " brass cap, marked as shown below, flush with ground and in a mound of stone 2 foot diameter. From which:

A 14" Douglas Fir alive and vigorous with a healed blaze, bears South 21° East, a distance of 40.65 feet.

SEE SURVEY NUMBER 018-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

From the iron pipe monument

### **NEW BEARING OBJECTS:**

A 14" Douglas Fir bears North 8° East, a distance of 53.00 feet, marked W 1/16 S10 BT.

This corner falls on the West side of a North/South running fenceline.

I hereby certify that the corner was perpetuated on March 10, 2015.

Witness: Thomas J. Kopp

PROFESSIONAL
LAND SUBVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015

T 1 S R 40 E
W 1/16
S 10
S 15
1980
OPLS 645

UNION COUNTY
SURVEYOR

Date Received 3/20/15

Date Filed By 1/20/15

File Number 086-7015R

I used a steel tape and magnetic compass in the establishment of the new accessory. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing tree.