
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

None



No record of subsequent monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

See Union County Survey 034-1996

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportioned position I set a  $2\frac{1}{2}$ " x 30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap marked as shown below, 30" in the ground with ring of stone, from which:

NEW BEARING TREES:

A 20" Ponderosa Pine bears N78°E, 24.60 feet, marked N 1/16 S17 BT. A 10" Douglas Fir bears N52°W, 7.24 feet, marked N 1/16 S18 BT.

I hereby certify that the corner was monumented on August 12, 1996. Witness: Mark Durbin, Jeff Madsen


> REGISTERED **PROFESSIONAL** LAND SURVEYOR

> > P. Peterser

OREGON

JEFFERY P. PETERSEN 2625

Renewal Date: December, 31 1996



UNION COUNTY **SURVEYOR** Date Received \$2-15-96 Date Filed 8-15 - 96 Filed By R. RUBINSON, DENLY File Number <u>688</u>-1996R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. Attached brass washer marked OPLS 2625 to the BT blaze.