CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 018-2015



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron rod with a 2 ½" aluminum cap marked as shown below, 25" in the ground. From which:

NEW BEARING OBJECTS:

A 15" Douglas Fir bears North 20° East, a distance of 27.05 feet, marked CW 1/16 S15 BT. A 6" Douglas Fir bears South 4° West, a distance of 43.50 feet, marked CW 1/16 S15 BT.

I set a steel fencepost approximately 1 foot North of corner monument.


I hereby certify that the corner was monumented on March 18, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the left side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

