




**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**

Corner originally established by James H. Hambleton in Union County Survey Number 54-75. Survey states: Set a 2" pipe w/ brass cap stamped.

T 1 S R 40 E L-22



**DESCRIPTION OF CORNER EVIDENCE FOUND:**


Found a 2 1/2" iron pipe, 12" above ground, with 2 1/2" brass cap marked as shown below.

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

From the Iron Pipe,

**NEW BEARING OBJECTS:**

A 16" White Fir bears South 87° West, a dist. of 6.55 ft., marked CW 1/16 S13 BT.  
A 12" Douglas Fir bears North 28° West, a dist. of 9.65 ft., marked CW 1/16 S13 BT.



A tripod of fence posts over the monument was in place when found.

Fence corner to West/South bearing fence lines falls Southwest approx. 1 ft.

I hereby certify that the corner was perpetuated on May 19, 2022.

Witness: Kyle A. Tucker

**UNION COUNTY SURVEYOR**  
Date Received 6/3/22  
Date Filed 6/3/22  
Filed By [Signature]  
File Number 015-2022R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

**REGISTERED PROFESSIONAL LAND SURVEYOR**  
[Signature]  
OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2023