
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None

T1S R40 EM-10



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey No. 014-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin with a 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 28" in the ground, with a collar of stone 2 foot diameter. From which:

NEW BEARING TREES:

A 17" White Fir bears South 74° East, a distance of 29.00 feet, marked SW 1/16 S16 BT.

A 9" Douglas Fir bears North 25° West, a distance of 20.80 feet, marked SW 1/16 S16 BT.

I set a steel fencepost approximately 1 foot North of the corner monument.


I hereby certify that this corner was monumented on March 3, 2015.


Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2015





I used a steel tape and magnetic compass in the establishment of the new tree accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.