


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously Established.

T 1 S R 40 E P-06



DESCRIPTION OF CORNER EVIDENCE FOUND:

Boise Cascade Location tag on dead and down tree bears North approx. 15 ft..

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 18" iron pin, drilled 5" into a rock outcropping, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 7" Douglas Fir bears South 26° East a dist. of 27.30 ft., marked CW 1/16 S20 BT.
An 11" Douglas Fir bears South 75° West a dist. of 14.00 ft., marked CW 1/16 S20 BT.

Set fence post approx. 1 ft. West

Fence corner to South and West bearing fence lines Southwest approx. 5 ft.

I hereby certify that the corner was monumented on April 24, 2019.
Witness: Kyle A. Tucker


REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2021

UNION COUNTY
SURVEYOR

Date Received 5/1/2020
Date Filed 5/1/2020
Filed By [Signature]
File Number 032-7020R



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.