CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Not previously Established.

DESCRIPTION OF CORNER EVIDENCE FOUND:

Existing Boise Cascade Location tag on Northwest bearing

T1S R40 EQ-06 S 20

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 30" iron pin, 27" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

A 5" Douglas Fir bears South 1° West a dist. of 5.70 ft., marked SW 1/16 S20 BT. An 11" Douglas Fir bears North 37° West a dist. of 12.95 ft., marked SW 1/16 S20 BT.

Set fence post approx. 0.5 ft. North

Fence corner to North and East bearing fence lines bears North 80° East approx. 12 ft.

I hereby certify that the corner was monumented on April 24, 2019. Witness: Kyle A. Tucker

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JEFFREY S. HSU 83571

Benewal Date: June 30, 2021

GRIFFITH BAGET T1S R40E SW 1/16 S20 **OPLS 83571** 2020

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 14° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.

UNION COUNTY SURVEYOR File Number 031- ZUZUR