CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 021-2015

S 20

T1S R40 ER-06

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a $5/8" \times 30"$ iron rod with a 2 ½" aluminum cap marked as shown below, 30" in the ground. From which:

NEW BEARING OBJECTS:

An 11" Lodge Pole Pine bears South 24° West, a distance of 22.00 feet, marked W 1/16 S29 BT.

A 12" Douglas Fir bears North 57° West, a distance of 31.35 feet, marked W 1/16 S20 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on April 17, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SUPVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

S20 W 1/16 S29 2015 OPLS 83571

UNION COUNTY SURVEYOR

Date Received

Date Filed

Filed By ___

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the left side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.