## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

### HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

## DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 013-2015

# DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a  $5/8" \times 30"$  iron pin with a 2 ½" aluminum cap marked as shown below, 30" in the ground. From which:

### NEW BEARING TREES:

A 6" White Fir bears South 30° West, a distance of 7.20 feet, marked CN 1/16 S29 BT. A 12" White Fir bears North 20° West, a distance of 17.85 feet, marked CN 1/16 S29 BT.

I set a steel fencepost approximately 1 foot South of the corner monument.

I hereby certify that this corner was monumented on March 2, 2015.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571


Renewal Date: June 30, 2015

C N 1/16 | S29 C 2015 OPLS 83571

T1S R40 ES-07

29

S



I used a steel tape and magnetic compass in the establishment of the new bearing trees. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.