
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 041-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a $5/8" \times 30"$ iron rod with a 2 ½" aluminum cap marked as shown below, 29" in the ground. From which:

NEW BEARING OBJECTS:

An 11" Douglas Fir bears North 63° East, a distance of 33.85 feet, marked N 1/16 S26 BT. An 8" Douglas Fir bears North 83° West, a distance of 13.55 feet, marked N 1/16 S27 BT.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on June 25, 2015.

Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571


Renewal Date: June 30, 2017

UNION COUNTY
SURVEYOR

Date Received 6/27/15

Date Filed 6/27/15

File Number 115-2015/



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.