


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. S-21

History of original corner establishment:

None .



Description of corner evidence found:

None .

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1 1/4" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E:  
 A 11" Fir bears N64°E., 22.4 ft. scribed N1/16S25 BT.  
 A 12" Fir bears S42°W., 31.5 ft. scribed N1/16S26 BT.  
 Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' south of the corner.

TLS R40E  
N1/16

S26 + S25

OR PLS 1051  
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland  
Troy Phillips

July 29, 1981

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of.....County.....Surveyor..... County of.....Union.....  
 State of.....Oregon..... I hereby certify that the within instrument was filed in this office  
 for record on the 10th day of.....August....., 19.81.

HOWARD L. PERRY  
(COUNTY OFFICIAL)

by *Harry J. Laughlin*  
(DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received \_\_\_\_\_

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 178-84 B