CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

SEE SURVEY NUMBER 013-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 $\frac{1}{2}$ " x 30" aluminum pipe with a 2 $\frac{1}{2}$ " aluminum cap marked as shown below, 27" in the ground. From which:

NEW BEARING TREES:

A 15" White Fir bears North 42° East, a distance of 20.30 feet, marked C1/4 S29 BT. A 19" White Fir bears South 60° East, a distance of 45.05 feet, marked C1/4 S29 BT. A 17" White Fir bears South 56° West, a distance of 10.65 feet, marked C1/4 S29 BT.

A 4" White Fir bears North 6° East, a distance of 27.80 feet, marked X BT.

I set a steel fencepost approximately 1 foot West of the corner monument.

I hereby certify that this corner was monumented on March 2, 2015.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571


Renewal Date: June 30, 2015

T1S R40E 2015
OPLS 83571

T1S R40 ET-07

29

S



I used a steel tape and magnetic compass in the establishment of the new bearing trees. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the new bearing tree. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.