


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

Index File No. T-19



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 1 1/4" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E;

A 12" Fir bears S10°E., 12.7 ft. scribed C1/4S26 BT.

A 12" Fir bears N69°W., 8.0 ft. scribed C1/4S26 BT.

Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' south of the corner.

T1S R40E

C1/4 + S26

OR PLS 1051
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland
Troy Phillips

July 30, 1981

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

**OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051**

Office of.....County..Surveyor..... County of..Union.....

State of..Oregon..... I hereby certify that the within instrument was filed in this office

for record on the..10th day of..August....., 19.81

HOWARD L. PERRY
(COUNTY OFFICIAL)

by *Gary L. Langfitt*
(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 20.270

Date Filed _____

By _____

File No. 180-84 B