


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

Index File No. U-21



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground.
 From which by magnetic declination of N20°E:
 A 14" Tamarac bears N09°E., 74.3 ft. scribed S1/16S25 BT.
 A 13" Fir bears N50°W., 34.7 ft. scribed S1/16S26 BT.
 Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' north of the corner.

T1S R40E
S1/16

S26 + S25

OR PLS 1051
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland
Troy Phillips

July 29, 1981

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of...County...Surveyor..... County of..Union.....

State of...Oregon..... I hereby certify that the within instrument was filed in this office

for record on the 10th day of...August....., 1981

Howard L. Perry
(COUNTY OFFICIAL)

by *Karen J. Langht*
(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 8.27.81

Date Filed _____

By _____

File No. 183-84 R