


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-19

**History of original corner establishment:**

Corner was originally established by Henry Meldrum, Deputy Surveyor, under G.L.O. contract No. 450, during August, 1882. Surveyors General's notes state: "Set a post 3 ft. long, 3 ins. sq., 24 ins. in the ground, for 1/4 sec. cor., mkd. 1/4S on N. face; from which a fir 7 ins. diam. bears S27°E., 20 lks. dist. mkd., 1/4S BT. A fir 10 ins. diam., bears N42°E., 16 lks. dist. mkd., 1/4S BT."



**Description of corner evidence found:**

Found no trace of record post or BTs.

**Description of monument and accessories established to perpetuate the original location of this corner:**

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 25" in the ground. From which by magnetic declination of N20°E: A 9" fir bears S58°E., 22.8 ft. scribed 1/4S35 BT. A 10" tamarac bears N04°W., 26.8 ft. scribed 1/4S26 BT. Painted blazes red and 6" red band around. Placed 54-3s and brass washers stamped PLS 1051 on BTs. Placed 54-4 on a steel fence post 5' east of the corner.

T1S R40E  
S26  
1/4 +  
S35  
OR PLS 1051  
1981

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland  
Troy Phillips

July 29, 1981

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Barry B. Barbour*  
**OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051**

Office of County Surveyor..... County of... Union.....  
State of Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the 10th day of August....., 1981  
**HOWARD L. PERRY**..... by *Harry J. Langley*  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>	
Date Received	_____
Date Filed	_____
By	_____
File No.	<u>186-84R</u>