


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

None.

T 1 S R 40 E W-10



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 016-2019

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE LOCATION OF THIS CORNER:

At position determined by survey I set a 5/8" x 30" iron pin, 26" in the ground, with 2 1/2" aluminum cap marked as shown below with 2' collar of stone, from which:

NEW BEARING OBJECTS:

A 5" Ponderosa Pine bears South 58° East a dist. of 5.95 ft., marked NW 1/16 S33 BT.
A 6" Douglas Fir bears North 48° West a dist. of 6.20 ft., marked NW 1/16 S33 BT.

West and North bearing fence corner falls approx. South 65° East, a dist. of 3'.

Boise Cascade location tag bears North approx. 36' on 14" diam. Douglas Fir.

I hereby certify that the corner was monumented on July 8, 2019.

Witness: Kyle A. Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2021

BAGETT - GRIFFITH & BLACKMAN

T1S R40E

NW 1/16 · S33

2019

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 7/16/19

Date Filed 7/16/19

Filed By [Signature]

File Number 038-2019R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.