
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

## DESCRIPTION OF CORNER EVIDENCE FOUND:

None



See Survey Number 041-2015

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a  $5/8" \times 30"$  iron rod with a 2 12" aluminum cap marked as shown below, 29" in the ground. From which:

## **NEW BEARING OBJECTS:**

A 6" Ponderosa Pine bears North  $51^{\circ}$  East, a distance of 3.90 feet, marked CN 1/16 S34 BT. A 5" Ponderosa Pine bears North  $72^{\circ}$  West, a distance of 5.20 feet, marked CN 1/16 S34 BT.

I set a steel fencepost approximately 1 foot North of corner monument.


I hereby certify that the corner was monumented on June 25, 2015.


Witness: Thomas J. Kopp

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017





I used a steel tape and magnetic compass in the establishment of the new accessories. I used 16° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.